

COPY

EDMUND G. BROWN JR., Attorney General
of the State of California
ARTHUR D. TAGGART
Supervising Deputy Attorney General
GEOFFREY S. ALLEN, State Bar No. 193338
Deputy Attorney General
1300 I Street, Suite 125
P.O. Box 944255
Sacramento, CA 94244-2550
Telephone: (916) 324-5341
Facsimile: (916) 327-8643
E-mail: Geoffrey.Allen@doj.ca.gov

Attorneys for Complainant

**BEFORE THE
DEPARTMENT OF CONSUMER AFFAIRS
FOR THE BUREAU OF AUTOMOTIVE REPAIR
STATE OF CALIFORNIA**

In the Matter of the Accusation Against:

LARRY R. SAENZ, OWNER
K & A PAINT & BODY

Respondent.

Case No. 77/07-45

OAH No. 2008080148

**DEFAULT DECISION
AND ORDER**

[Gov. Code, §11520]

FINDINGS OF FACT

1. On or about April 15, 2008, Complainant Sherry Mehl ("Complainant"), in her official capacity as the Chief of the Bureau of Automotive Repair ("Bureau"), Department of Consumer Affairs, filed Accusation No. 77/07-45 ("Accusation") against Larry R. Saenz a.k.a. Larry Ramirez, owner, K & A Paint & Body ("Respondent") before the Director of Consumer Affairs ("Director").

2. On or about March 19, 2001, the Bureau issued Automotive Repair Dealer Registration Number AA 214658 ("Registration") to Respondent. The Registration was delinquent from January 31, 2004, to October 11, 2005, and from January 31, 2006, to June 16, 2006. The Registration expired on January 31, 2008.

3. On or about April 28, 2008, Constance Ward, an employee of the Department of Justice, served by Certified and First Class Mail a copy of the Accusation,

1 Statement to Respondent, Notice of Defense, Request for Discovery, and Government Code
2 sections 11507.5, 11507.6, and 11507.7 to Respondent's address of record with the Bureau,
3 which was and is: 1539 East Tulare Avenue, Tulare, California 93274. A copy of the Accusation
4 is attached as exhibit A, and is incorporated herein by reference.

5 4. Service of the Accusation was effective as a matter of law under the
6 provisions of Business and Professions Code section 124.

7 5. A Notice of Hearing was served by mail at Respondent's address of record
8 and it informed him that an administrative hearing in this matter was scheduled to begin on
9 November 13, 2008. Respondent failed to appear at that hearing.

10 6. Government Code section 11506 states, in pertinent part:

11 (c) The respondent shall be entitled to a hearing on the merits if the
12 respondent files a notice of defense, and the notice shall be deemed a specific
13 denial of all parts of the accusation not expressly admitted. Failure to file a notice
of defense shall constitute a waiver of respondent's right to a hearing, but the
agency in its discretion may nevertheless grant a hearing.

14 7. Government Code section 11520 states, in pertinent part:

15 (a) If the respondent either fails to file a notice of defense or to appear at
16 the hearing, the agency may take action based upon the respondent's express
admissions or upon other evidence and affidavits may be used as evidence without
any notice to respondent.

17 8. Pursuant to its authority under Government Code section 11520, the
18 Director finds Respondent is in default. The Director will take action without further hearing
19 and, based on the evidence on file herein, finds that the allegations in the Accusation.
20

21 9. The total cost for investigation and enforcement in connection with the
22 Accusation are \$6,717.25 as of November 12, 2008.

23 DETERMINATION OF ISSUES

24 1. Based on the foregoing findings of fact, Respondent has subjected his
25 Registration to discipline.

26 2. A copy of the Accusation is attached.

27 3. The agency has jurisdiction to adjudicate this case by default.

28 4. The Director is authorized to revoke Respondent's Registration based upon

1 the following violations alleged in the Accusation:

- 2 a. Respondent violated Business and Professions Code ("Code")
3 section 9884.7, subdivision (a)(1), in that in Respondent made untrue or misleading;
4 b. Respondent violated Code section 9884.7, subdivision (a)(4), in
5 that Respondent committed acts which constitute fraud;
6 c. Respondent violated Code section 9884.7, subdivision (a)(6), in
7 that Respondent violated provisions of the Automotive Repair Act;
8 d. Respondent violated Code section 9884.7, subdivision (a)(6), in
9 that Respondent violated regulations promulgated pursuant to the Automotive Repair
10 Act; and,
11 e. Respondent violated Code section 9884.7, subdivision (a)(7), in
12 that, Respondent wilfully departed from or disregarded accepted trade standards for good
13 and workmanlike repair.

14 ///

15 ///

16 ///


1 ORDER

2 IT IS SO ORDERED that the Registration heretofore issued to Respondent is
3 revoked.

4 Pursuant to Government Code section 11520, subdivision (c), Respondent may
5 serve a written motion requesting that the Decision be vacated and stating the grounds relied on
6 within seven (7) days after service of the Decision on Respondent. The agency in its discretion
7 may vacate the Decision and grant a hearing on a showing of good cause, as defined in the
8 statute.

9 This Decision shall become effective on January 30, 2009.

10 It is so ORDERED December 23, 2008

11
12 

13 PATRICIA HARRIS
14 Deputy Director, Board/Bureau Support
15 Department of Consumer Affairs

16 30605664.wpd
17 DOJ docket number:SA2007102609

18 Attachment:

19 Exhibit A: Accusation No.77/07-45
20
21
22
23
24
25
26
27
28

Exhibit A

Accusation No. 77/07-45

1 EDMUND G. BROWN JR., Attorney General
of the State of California
2 ARTHUR D. TAGGART
Supervising Deputy Attorney General
3 GEOFFREY S. ALLEN, State Bar No. 193338
Deputy Attorney General
4 California Department of Justice
1300 I Street, Suite 125
5 P.O. Box 944255
Sacramento, CA 94244-2550
6 Telephone: (916) 322-5318
Facsimile: (916) 324-5567

7 Attorneys for Complainant
8

9 **BEFORE THE**
DEPARTMENT OF CONSUMER AFFAIRS
10 **FOR THE BUREAU OF AUTOMOTIVE REPAIR**
11 **STATE OF CALIFORNIA**

12 In the Matter of the Accusation Against:

Case No. 77107-45

13 **K & A PAINT & BODY**
1539 East Tulare Avenue
14 Tulare, CA 93274
15 **LARRY R. SAENZ, AKA**
LARRY RAMIREZ, OWNER

ACCUSATION

16 Automotive Repair Dealer Reg. No. AA 214658

17 Respondent.
18

19 Complainant alleges:

20 **PARTIES**

21 1. Sherry Mehl ("Complainant") brings this Accusation solely in her official
22 capacity as the Chief of the Bureau of Automotive Repair ("Bureau"), Department of Consumer
23 Affairs.

24 **Automotive Repair Dealer Registration**

25 2. On or about March 19, 2001, the Bureau issued Automotive Repair Dealer
26 Registration Number AA 214658 ("Registration") to Larry R. Saenz, also known as
27 Larry Ramirez ("Respondent"), doing business as K & A Paint & Body. The Registration was

28 ///

delinquent from January 31, 2004, to October 11, 2005, and from January 31, 2006, to June 16, 2006. The Registration expired on January 31, 2008.

STATUTORY PROVISIONS

3. Business and Professions Code ("Code") section 9884.7 states, in pertinent part:

(a) The director, where the automotive repair dealer cannot show there was a bona fide error, may refuse to validate, or may invalidate temporarily or permanently, the registration of an automotive repair dealer for any of the following acts or omissions related to the conduct of the business of the automotive repair dealer, which are done by the automotive repair dealer or any automotive technician, employee, partner, officer, or member of the automotive repair dealer.

(1) Making or authorizing in any manner or by any means whatever any statement written or oral which is untrue or misleading, and which is known, or which by the exercise of reasonable care should be known, to be untrue or misleading.

(4) Any other conduct which constitutes fraud.

(6) Failure in any material respect to comply with the provisions of this chapter or regulations adopted pursuant to it.

(7) Any willful departure from or disregard of accepted trade standards for good and workmanlike repair in any material respect, which is prejudicial to another without consent of the owner or his or her duly authorized representative.

(b) Except as provided for in subdivision (c), if an automotive repair dealer operates more than one place of business in this state, the director pursuant to subdivision (a) shall only invalidate temporarily or permanently the registration of the specific place of business which has violated any of the provisions of this chapter. This violation, or action by the director, shall not affect in any manner the right of the automotive repair dealer to operate his or her other places of business.

(c) Notwithstanding subdivision (b), the director may invalidate temporarily or permanently, the registration for all places of business operated in this state by an automotive repair dealer upon a finding that the automotive repair dealer has, or is, engaged in a course of repeated and willful violations of this chapter, or regulations adopted pursuant to it.

4. Code section 9884.8 states:

All work done by an automotive repair dealer, including all warranty work, shall be recorded on an invoice and shall describe all service work done and parts supplied. Service work and parts shall be listed separately on the invoice, which shall also state separately the subtotal prices for service work and for parts, not including sales tax, and shall state separately the sales tax, if any, applicable to each. If any used, rebuilt, or reconditioned parts are supplied, the

1 invoice shall clearly state that fact. If a part of a component system is composed
2 of new and used, rebuilt or reconditioned parts, that invoice shall clearly state that
3 fact. The invoice shall include a statement indicating whether any crash parts are
4 original equipment manufacturer crash parts or nonoriginal equipment
5 manufacturer aftermarket crash parts. One copy of the invoice shall be given to
6 the customer and one copy shall be retained by the automotive repair dealer.

7 5. Code section 9884.9 states, in pertinent part:

8 (a) The automotive repair dealer shall give to the customer a written
9 estimated price for labor and parts necessary for a specific job. No work shall be
10 done and no charges shall accrue before authorization to proceed is obtained from
11 the customer. No charge shall be made for work done or parts supplied in excess
12 of the estimated price without the oral or written consent of the customer that
13 shall be obtained at some time after it is determined that the estimated price is
14 insufficient and before the work not estimated is done or the parts not estimated
15 are supplied. Written consent or authorization for an increase in the original
16 estimated price may be provided by electronic mail or facsimile transmission
17 from the customer. The bureau may specify in regulation the procedures to be
18 followed by an automotive repair dealer if an authorization or consent for an
19 increase in the original estimated price is provided by electronic mail or facsimile
20 transmission. If that consent is oral, the dealer shall make a notation on the work
21 order of the date, time, name of person authorizing the additional repairs and
22 telephone number called, if any, together with a specification of the additional
23 parts and labor and the total additional cost, and shall do either of the following:

24 (1) Make a notation on the invoice of the same facts set forth in the
25 notation on the work order.

26 (2) Upon completion of the repairs, obtain the customer's signature or
27 initials to an acknowledgment of notice and consent, if there is an oral consent of
28 the customer to additional repairs, in the following language:

"I acknowledge notice and oral approval of an increase in the original estimated
price.

(signature or initials)"

Nothing in this section shall be construed as requiring an automotive
repair dealer to give a written estimated price if the dealer does not agree to
perform the requested repair.

(c) In addition to subdivisions (a) and (b), an automotive repair dealer,
when doing auto body or collision repairs, shall provide an itemized written
estimate for all parts and labor to the customer. The estimate shall describe labor
and parts separately and shall identify each part, indicating whether the
replacement part is new, used, rebuilt, or reconditioned. Each crash part shall be
identified on the written estimate and the written estimate shall indicate whether
the crash part is an original equipment manufacturer crash part or a nonoriginal
equipment manufacturer aftermarket crash part.

6. Code section 9884.13 states, in pertinent part, that the expiration of a valid
registration shall not deprive the Director of jurisdiction to proceed with a disciplinary

proceeding against an automotive repair dealer or to render a decision invalidating a registration temporarily or permanently.

7. Code section 477 provides, in pertinent part, that “Board” includes “bureau,” “commission,” “committee,” “department,” “division,” “examining committee,” “program,” and “agency.” “License” includes certificate, registration or other means to engage in a business or profession regulated by the Code.

REGULATORY PROVISIONS

8. California Code of Regulations, title 16, (“Regulation”) section 3353, states, in pertinent part:

No work for compensation shall be commenced and no charges shall accrue without specific authorization from the customer in accordance with the following requirements:

(e) **Revising an Itemized Work Order.** If the customer has authorized repairs according to a work order on which parts and labor are itemized, the dealer shall not change the method of repair or parts supplied without the written, oral, or electronic authorization of the customer. The authorization shall be obtained from the customer as provided in subsection (c) and Section 9884.9 of the Business and Professions Code.

9. Regulation section 3364 states:

(a) An automotive repair dealer shall not remove, paint over, or otherwise deface any label or sticker which has been affixed to the doorpost, dash, underhood, windshield, or other location on a vehicle, and which contains identifying information regarding the vehicle or its emission control system components. An automotive repair dealer shall replace any such label or sticker which would otherwise be destroyed as part of the repair process, unless the replacement label or sticker is not reasonably available.

10. Regulation section 3365 states:

The accepted trade standards for good and workmanlike auto body and frame repairs shall include, but not be limited to, the following:

(a) Repair procedures including but not limited to the sectioning of component parts, shall be performed in accordance with OEM service specifications or nationally distributed and periodically updated service specifications that are generally accepted by the autobody repair industry.

(b) All corrosion protection shall be applied in accordance with manufacturers' specifications or nationally distributed and periodically updated service specifications that are generally accepted by the autobody repair industry.

///

1 **COST RECOVERY**

2 11. Code section 125.3 provides, in pertinent part, that a Board may request
3 the administrative law judge to direct a licensee found to have committed a violation or
4 violations of the licensing act to pay a sum not to exceed the reasonable costs of the investigation
5 and enforcement of the case.

6 **UNDERCOVER OPERATION NO. 1 - 2000 PONTIAC GRAND PRIX**

7 12. On or about January 22, 2007, a Tulare County District Attorney Criminal
8 Investigator using the alias Nancy Lee ("Operator #1"), brought a Bureau-documented 2000
9 Pontiac Grand Prix, California License #5MQY671, to Respondent's facility for collision
10 repairs. Operator #1 spoke with a male who was identified as Mario. Operator #1 provided
11 Mario with Insurance Estimate Number 306022, prepared by Western United Insurance
12 Company, dated January 22, 2007, for \$5,750.99 ("Insurance Estimate No. 306022"), and
13 requested that the repairs be made in accordance with the estimate.

14 13. On or about January 23, 2007, Respondent told Operator #1 that he would
15 not charge her the \$500 insurance deductible and that he would perform the vehicle repairs
16 according to Insurance Estimate No. 306022.

17 14. On or about January 25, 2007, Respondent called Western United
18 Insurance Company and agreed to perform the vehicle repairs according to Insurance Estimate
19 No. 306022.

20 15. On or about February 8, 2007, Respondent negotiated a check issued by
21 Western United Insurance Company, payable to K & A Paint & Body, in the amount of
22 \$5,250.97, for the vehicle repairs.

23 16. On or about February 15, 2007, Operator #1 returned to Respondent's
24 facility to retrieve the vehicle. Respondent stated that the vehicle repairs had been made
25 according to Insurance Estimate No. 306022, and that he would not charge the \$500 deductible.
26 As a final invoice, Respondent provided Operator #1 with Estimate Report No. 695, dated
27 February 15, 2007.

28 ///

1 17. On or about March 6, 2007, the Bureau inspected the vehicle using
2 Insurance Estimate No. 306022 as a reference. The inspection revealed the following:
3 a. Respondent failed to remove and replace a wheel.
4 b. Respondent failed to replace the left front door shell with a new General
5 Motors ("GM") part. Instead, the part was replaced with a used part.
6 c. Respondent failed to replace the left door adhesive molding with a new
7 GM part. Instead, the part was replaced with a used part.
8 d. Respondent failed to replace the left door adhesive nameplate with a new
9 part.
10 e. Respondent failed to replace the left quarter outer panel with a new GM
11 part. Instead, the part was repaired and refinished.
12 f. Respondent failed to refinish the left quarter panel pillar.
13 g. Respondent failed to refinish the left quarter panel edge.
14 h. Respondent failed to remove and repair the left quarter lock pillar
15 reinforcement.
16 i. Respondent failed to remove and replace the left quarter adhesive molding
17 with a new GM part.
18 j. Respondent failed to blend the luggage lid.
19 k. Respondent failed to blend the roof panel.
20 l. Respondent failed to remove and install the luggage lid spoiler.
21 m. Respondent failed to replace the rear bumper cover with a new GM part.
22 Instead, the part was replaced with an aftermarket part.

23 **FIRST CAUSE FOR DISCIPLINE**

24 **(Untrue or Misleading Statements)**

25 18. Respondent is subject to disciplinary action pursuant to Code section
26 9884.7, subdivision (a)(1), in that in or around February 2007, Respondent made or authorized
27 statements which he knew, or in the exercise of reasonable care, he should have known to be
28 untrue or misleading. Respondent falsely represented to Operator #1 and Western United

1 Insurance Company that Operator #1's vehicle had been repaired pursuant to Insurance Estimate
2 No. 306022; however, Respondent failed to perform services or repairs, as more particularly set
3 forth in paragraph 17 subparagraphs a through m, above.

4 **SECOND CAUSE OF DISCIPLINE**

5 **(Fraudulent Acts)**

6 19. Respondent is subject to disciplinary action pursuant to Code section
7 9884.7, subdivision (a)(4), in that in or around February 2007, Respondent committed acts which
8 constitute fraud by receiving payment from Western United Insurance Company for repairs that
9 Respondent had not performed, for parts that he had not replaced with new parts, and his failure
10 to replace some parts at all, as more fully set forth in paragraph 17, subparagraphs a through m,
11 above.

12 **THIRD CAUSE FOR DISCIPLINE**

13 **(Failure to Comply with Provisions of the Automotive Repair Act)**

14 20. Respondent is subject to disciplinary action pursuant to Code section
15 9884.7, subdivision (a)(6), in that in or around February 2007, Respondent violated the
16 provisions of the Code, as follows:

17 a. **Section 9884.8:** Regarding Report No. 695, Respondent failed to
18 separately list all service work performed and parts supplied regarding the repairs to Operator
19 #1's vehicle.

20 b. **Section 9884.9, subdivision (c):** Respondent failed to give Operator #1
21 an itemized written estimate for the auto body repairs, including a list or description of all labor,
22 and parts and whether the crash part was an original equipment manufacturer crash part, a non-
23 original equipment manufacturer aftermarket crash part, or a used part.

24 **FOURTH CAUSE FOR DISCIPLINE**

25 **(Failure to Comply with Regulations Pursuant to the Automotive Repair Act)**

26 21. Respondent is subject to disciplinary action pursuant to Code section
27 9884.7, subdivision (a)(6), in that in or around February 2007, Respondent failed to comply with

28 ///

1 Regulation 3353, subdivision (e), by changing the method of repairs or parts supplied, as set
2 forth in paragraph 17, subparagraphs a through m, above, without Operator #1's authorization.

3 **UNDERCOVER OPERATION NO. 2 - 1988 TOYOTA CAMRY**

4 22. On or about June 7, 2007, Cynthia Jessup, a Bureau undercover operator
5 ("Operator #2"), accompanied by an undercover Tulare County District Attorney Criminal
6 Investigator, brought a Bureau-documented 1998 Toyota Camry, California License # 4ARE088,
7 to Respondent's facility for collision repairs. Operator #2 gave Respondent Insurance Estimate
8 Number 01-AM97664, prepared by California State Automobile Association ("CSAA"), dated
9 June 4, 2007, totaling \$3,525.24, and told Respondent to repair the vehicle in accordance with
10 that estimate.

11 23. Respondent provided Operator #2 with his Estimate Report Number 823,
12 dated June 7, 2007, that stated, "Repair as per Est ID #01-AM97664", in the amount of
13 \$3,025.24.

14 24. On or about June 7, 2007, Respondent contacted Mr. Sullivan at CSAA.
15 Respondent deemed that Items 1 and 2 on the estimate were unnecessary and Mr. Sullivan
16 agreed to remove them. CSAA Estimate ID Number 01-AM97664, dated June 7, 2007, in the
17 amount of \$2,925.13 was generated ("Revised Insurance Estimate No. 01-AM97664"), and
18 Respondent agreed to perform the vehicle repairs accordingly.

19 25. On or about June 18, 2007, Respondent negotiated a check issued by
20 CSAA, payable to K & A Paint & Body and Cynthia Jessup in the amount of \$2,925.13, for the
21 vehicle repairs, which Respondent negotiated without Cynthia Jessup's signature. Cynthia
22 Jessup neither executed the check nor gave anyone permission to sign it on her behalf.

23 26. On or about June 26, 2007, Operator #2, accompanied by another
24 undercover Bureau operator, returned to Respondent's facility to retrieve the vehicle.
25 Respondent told Operator #2 that the vehicle repairs had been completed. Respondent charged
26 Operator #2 \$300 of the \$500 insurance deductible, which Operator #2 paid in cash. Operator #2
27 was provided with a copy of Report Number 823, dated June 26, 2007.

28 ///

1 27. On or about July 9, 2007, the Bureau inspected the vehicle using Revised
2 Insurance Estimate No. 01-AM97664 as a reference. The inspection revealed the following:

- 3 a. Respondent failed to remove and install the right front door belt molding.
4 b. Respondent failed to remove and install the right front upper door window
5 frame molding.
6 c. Respondent failed to remove and install the right front door mirror.
7 d. Respondent failed to remove and install the right front door handle.
8 e. Respondent failed to remove and replace the right rear door adhesive
9 molding with a new part.
10 f. Respondent failed to remove and replace the right combination lamp
11 assembly with a new Toyota part. Instead, the part was replaced with an aftermarket part.
12 g. Respondent failed to remove and replace the rear bumper cover. Instead,
13 the part was repaired and painted.

14 **FIFTH CAUSE FOR DISCIPLINE**

15 **(Untrue or Misleading Statements)**

16 28. Respondent is subject to disciplinary action pursuant to Code section
17 9884.7, subdivision (a)(1), in or around June 2007, Respondent made or authorized statements
18 which he knew, or in the exercise of reasonable care, he should have known to be untrue or
19 misleading. Respondent falsely represented to Operator #2 and CSAA that Operator #2's
20 vehicle had been repaired pursuant to Revised Insurance Estimate No. 01-AM97664; however,
21 Respondent failed to perform services or repairs, as more particularly set forth in paragraph 27,
22 subparagraphs a through g, above.

23 **SIXTH CAUSE OF DISCIPLINE**

24 **(Fraudulent Acts)**

25 29. Respondent is subject to disciplinary action pursuant to Code section
26 9884.7, subdivision (a)(4), in that in or around June 2007, Respondent committed acts which
27 constitute fraud, as follows:

28 ///

1 a. Respondent received payment for repairs that had not been performed,
2 parts that had not been replaced with new parts or failing to replace parts at all, as more fully set
3 forth in paragraph 27, subparagraphs a through g, above.

4 b. Respondent negotiated a check requiring Operator #2's signature, which
5 Operator #2 had not signed, as more fully set forth in paragraph 26, above.

6 **SEVENTH CAUSE FOR DISCIPLINE**

7 **(Failure to Comply with Provisions of the Automotive Repair Act)**

8 30. Respondent is subject to disciplinary action pursuant to Code section
9 9884.7, subdivision (a)(6), in that in or around June 2007, Respondent violated the provisions of
10 the Code, as follows:

11 a. **Section 9884.8:** Regarding Estimate Report Number 823, Respondent
12 failed to separately list all service work performed and parts supplied.

13 b. **Section 9884.9, subdivision (a):** Respondent failed to obtain customer
14 authorization to repair the vehicle in accordance with Revised Insurance Estimate No. 01-
15 AM97664, dated June 7, 2007.

16 c. **Section 9884.9, subdivision (c):** Respondent failed to provide an
17 itemized written estimate for the auto body repairs, including a list or description of all labor and
18 parts and whether the crash part was an original equipment manufacturer crash part, a non-
19 original equipment manufacturer aftermarket crash part, or a used part.

20 **EIGHTH CAUSE FOR DISCIPLINE**

21 **(Failure to Comply with Regulations Pursuant to the Automotive Repair Act)**

22 31. Respondent is subject to disciplinary action pursuant to Code section
23 9884.7, subdivision (a)(6), in that in or around June 2007, Respondent failed to comply with
24 Regulation 3353, subdivision (e), by changing the method of repairs or parts supplied, as set
25 forth in paragraph 27, subparagraphs a through g, above, without Operator #2's authorization.

26 ///

27 ///

28 ///

1 **NINTH CAUSE FOR DISCIPLINE**

2 **(Departure From Trade Standards Pursuant to Regulations)**

3 32. Respondent is subject to disciplinary action pursuant to Code section
4 9884.7, subdivision (a)(7), in that in or around June 2007, Respondent wilfully departed from or
5 disregarded accepted trade standards for good and workmanlike repair, by failing to perform
6 auto body repairs that meet minimum requirements, as defined in the Regulations, as follows:

7 a. **Regulation 3364, subdivision (a):** Respondent defaced the vehicle
8 identification number by painting over it.

9 b. **Regulation 3365, subdivision (b):** Respondent failed to follow
10 procedures for corrosion protection by failing to refinish the lower edge of the replacement right
11 rear quarter panel, around the wheel opening, and inside the trunk; and, failed to paint the right
12 quarter panel and rear body panel.

13 **CONSUMER COMPLAINT (SCHNABEL) - 1971 CHEVROLET CHEVELLE**

14 33. On or about May 15, 2007, the Bureau received a Consumer Complaint
15 from Mr. Schnabel ("Consumer") regarding Respondent's failure to complete repairs to
16 Consumer's vehicle between in or around December 2006 and June 2007.

17 34. On or about December 6, 2006, Consumer agreed to pay Respondent
18 \$9,000 total for auto body repairs on his 1971 Chevrolet Chevelle, including the removal of the
19 body from the frame, replacement of the right quarter panel and trunk floor pan, sanding and
20 painting the body and frame, replacement of the steering and suspension bushings on the frame,
21 and reassembly. The Consumer paid Respondent a \$4,000 down payment. Respondent issued
22 Estimate Report No. 630, dated December 6, 2006 ("Estimate Report No. 630"), reflecting that
23 he had received a \$4,000 down payment and that the remaining balance was \$5,000. Respondent
24 gave the Consumer a copy of Estimate Report No. 630. The description of work on Estimate
25 Report No. 630 stated, "complete tear down install outers pull body sand and paint frame install
26 busing trunk floor complete body work put back together paintcomplete".

27 ///

28 ///

1 35. After approximately six months, the repairs had not been completed.
2 Respondent had removed the body from the frame, replaced the right quarter panel and trunk
3 floor pan and primed the vehicle exterior only. The Consumer retrieved his vehicle from
4 Respondent's facility and requested a refund, which was denied by Respondent.

5 **TENTH CAUSE FOR DISCIPLINE**

6 **(Failure to Comply with Provisions of the Automotive Repair Act)**

7 36. Respondent is subject to disciplinary action pursuant to Code section
8 9884.7, subdivision (a)(6), in that Respondent violated the provisions of the Code, as follows:

9 a. **Section 9884.8:** In or about June 2007, Respondent failed to give the
10 Consumer an invoice of parts provided and all service work performed on the Consumer's
11 vehicle.

12 b. **Section 9884.9, subdivision (c):** Regarding Estimate Report No. 630,
13 Respondent failed to separately list service work and parts to be supplied to repair the
14 Consumer's vehicle.

15 **OTHER MATTERS**

16 37. Pursuant to Code section 9884.7, subdivision (c), the Director may refuse
17 to validate, or may invalidate temporarily or permanently, the registrations for all places of
18 business operated in this state by Respondent Larry R. Saenz, also known as Larry Ramirez,
19 owner of K & A Paint & Body, upon a finding that said Respondent has, or is, engaged in a
20 course of repeated and willful violations of the laws and regulations pertaining to an automotive
21 repair dealer.

22 ///

23 ///

24 ///

25 ///

26 ///

27 ///

28 ///

1 PRAYER

2 **WHEREFORE**, Complainant requests that a hearing be held on the matters
3 herein alleged, and that following the hearing, the Director of Consumer Affairs issue a decision:

4 1. Temporarily or permanently invalidating Automotive Repair Dealer
5 Registration Number AA 214658 issued to Larry R. Saenz, also known as Larry Ramirez, doing
6 business as K & A Paint & Body;

7 2. Temporarily or permanently invalidating any other automotive repair
8 dealer Registration issued to Larry R. Saenz, also known as Larry Ramirez, doing business as
9 K & A Paint & Body;

10 3. Ordering Larry R. Saenz, also known as Larry Ramirez, to pay the
11 Director of Consumer Affairs the reasonable costs of the investigation and enforcement of this
12 case, pursuant to Code section 125.3; and,

13 4. Taking such other and further action as deemed necessary and proper.

14 DATED: 4-15-08

15
16
17 
18 SHERRY MEHL
19 Chief
20 Bureau of Automotive Repair
21 Department of Consumer Affairs
22 State of California
23 Complainant

20 03548110-SA2007102609
21 K&APaint&Body.wpd
22 [baf 11/20/07]